



- CONSTRUCTION DETAILS**
- REMOVE EXISTING 5-SECTION SIGNAL HEAD AND REPLACE WITH NEW LED 3-SECTION SIGNAL HEAD AS SHOWN ON THE PLAN.
 - INSTALL NEW LED 3-SECTION SIGNAL HEAD AS SHOWN ON THE PLAN.
 - INSTALL NEW SIGN R10-12(2) ON MAST ARM AS INDICATED ON THE PLAN.
 - USE EXISTING SIGNAL MAST ARM.
 - USE EXISTING CONDUIT.
 - USE HANDHOLE.
 - EXISTING CABINET AND CONTROLLER.

- GENERAL NOTES**
- ALL UNDERGROUND AND OVERHEAD UTILITIES SHOWN ON THESE PLANS ARE SCHEMATIC ONLY AND MAY NOT BE COMPLETE. THE CONTRACTOR SHALL BE RESPONSIBLE FOR NOTIFYING "MISS UTILITY" PRIOR TO CONSTRUCTION SO THAT ALL UTILITIES NOT BE LOCATED IN THE FIELD. IF THE CONTRACTOR PERCEIVES THAT A CONFLICT BETWEEN THE UTILITIES AND THE TRAFFIC SIGNAL WILL OCCUR, THE CONTRACTOR SHALL NOTIFY THE PROJECT ENGINEER IMMEDIATELY SO THAT THE CONFLICT MAY BE RESOLVED.
 - THE CONTRACTOR SHALL BE RESPONSIBLE FOR TERMINATING ALL SIGNAL CABLES TO THE APPROPRIATE TERMINALS PROPERLY LABELING EACH CABLE.
 - THE CONTRACTOR SHALL MAINTAIN THE CONTINUOUS OPERATION OF THE INTERCONNECT, VEHICULAR, PEDESTRIAN DETECTORS, AND LIGHTING DEVICES. IF ANY DEVICE IS DAMAGED BY THE CONTRACTOR, IT SHALL BE REPAIRED WITH 72 HOURS BY THE CONTRACTOR AT NO COST TO THE ADMINISTRATION.

GEOMETRIC LEGEND	
---	EXISTING
UTILITY LEGEND	
---	STORM DRAIN
---	GAS MAIN
---	WATER MAIN
---	SEWER MAIN
---	ELECTRIC CABLES
---	AERIAL CABLES
---	TELEPHONE CABLES
---	FIBER-OPTIC

NOTE:

CENTER SIGNAL HEADS NO. 2 AND 6 WITH CORRESPONDING LEFT TURN LANES.

APPROVALS

TEAM LEADER

ASSIST. DIR. CHIEF

DIVISION CHIEF

OFFICE DIRECTOR

REVISIONS

1. CHANGE US 50 E.P. LEFT TURN (EB & WB) TO EXCLUSIVE AND FLASHING RED ARROW

2. AS BUILT: INSTALL APSCPS AND RAMP

3. REPLACEMENT OF DAMAGED LOOP DETECTORS

SCALE: 1" = 20'

DATE: 12-30-1990

CONTRACT NO.: 2385512508332

DESIGNED BY: B. THOMPSON

DRAWN BY: B. THOMPSON

CHECKED BY:

F.A.P. NO.:

COUNTY: TALBOT

LOGMILE: 20005012.51

T.I.M.S. NO.:

TOD NO.:

TS NO. 348

DRAWING SG-01 OF 02

SHEET NO. 1 OF 2

SHA STATE OF MARYLAND
DEPARTMENT OF TRANSPORTATION
STATE HIGHWAY ADMINISTRATION
OFFICE OF TRAFFIC & SAFETY
TRAFFIC ENGINEERING DESIGN DIVISION
US 50 (OCEAN GATEWAY) AND DUTCHMAN'S LANE
EASTON, MARYLAND

TOD NO. XY131-03
SHA NO. 7A302851
US 50 @ Dutchman's Lane

BY: Mkbengele

PLOTTED: Friday, September 13, 2013 AT 01:28 PM
FILE: J:\DATA\M201\Design Files\SG-P001_M201.dgn